6/5

Public Works (1906) Department.

G.O., No. 4719

DATED 3-5-1906.

read

4/5/06

[Despatch Abstract.]

Large bungalow at Periyar in the Madura Dt. used as a rest house by inspecting officers

An estimate, amounting to Rs 620, for improving the ———, sanctioned.

110/4

262 of 06-07

Registered
3.5.06

P. W. 26.
2,000—7-7-06

3/5

Indexed. 4/5/06

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

IRRIGATION.
ACCOUNT.

Government of Madras.

PUBLIC WORKS DEPARTMENT.

Recd.	1906.	*Enclosures*	
Regd.		*Spare copies*	

G.O., No. 471 I., 3rd May 1906.

Large Bungalow at Periyar in the Madura district used as a rest-house by Inspecting officers

An estimate, amounting to Rs. 620, for improving the —, sanctioned.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Irrigation.
Account.

READ—the following papers :—

I

Letter—from C. A. SMITH, Esq., Superintending Engineer, VI Circle.
To—the Chief Engineer for Irrigation.
Dated—Madras, the 10th March 1906.
No.—14 C.E./Camp.

I have the honour to inform you that the large bungalow at Periyár is being used as a rest-house for inspecting officers. It is covered with corrugated sheets without any sort of covering over it with the result that during hot weather it is hardly safe for fear of sunstroke. It is therefore proposed to provide wooden ceiling underneath the roof throughout including the verandahs also, and the estimate herewith submitted provides for the same and I request your approval thereto. A plan of the building is also forwarded.

ENCLOSURE.

Report to accompany the estimate for improvements to Periyár big bungalow.

	RS.
Amount of estimate	620

The roof of the building consists of corrugated iron sheeting without tiles or other covering and during the hot weather it is unsafe to remain in the bungalow with one's head-uncovered for fear of sunstroke.

This estimate therefore provides for a wooden ceiling of planks ½" thick (jungle-wood) to both inner rooms and verandahs to be covered with two coats of wood oil. Joints to be rebated.

A. V. RAMALINGA AIYAR,
Executive Engineer, Madura Division.

II

Note by the Chief Engineer for Irrigation.

The Superintending Engineer, VI Circle, submits an estimate, amounting to Rs. 620, for improving the large bungalow at Periyár which is now being used as a rest-house by inspecting officers. As the roof of the bungalow has only a covering of corrugated iron sheets, it is stated that much inconvenience is felt by the occupants during the hot season. It is, therefore, proposed to provide wooden ceiling underneath the roof throughout including the verandahs. The estimate is recommended for sanction.

26*th April* 1906.

C. A. SMITH,
Ag. Chief Engineer for Irrigation.

Order—No. 471 I., dated 3rd May 1906.

The following estimate is sanctioned :—

Imperial.
Irrigation.
42. Major Works (Working Expenses).
Periyár Project.
Madura Division.
I. Extensions and Improvements.
I. Head Works.
K. Buildings.
Improving the large bungalow at Periyár.

	RS.
Estimate	620

2. This sanction is registered as No. 26 I. of 1906-1907.

(True Extract.)

C. A. SMITH,
Ag. Joint Secretary to Government,
Irrigation Branch.

To the Chief Engineer for Irrigation.
,, Superintending Engineer, VI Circle, with estimate.
,, Examiner, Public Works Accounts.

Forwarded to the

(By order.)

Ag. Deputy Registrar.

1,000—22-6-06.

NOTES.

PUBLIC WORKS DEPARTMENT.

Irrigation Branch

C. No. 1456 / 17.3.06

D. E. I.

Orders are requested if the Estᵉ may be checked for sanction.

17.3.06

Yes

17/3

C.E.I.

The estimate has been checked.

23.4.06

21/4/06.

D.S.

A draft order on the estimate is submitted and may if approved, be circulated to H.E. & the Hon'ble Mr. G. Stokes. ×

× In accordance with his special instructions re inspection bungalows

21.4.06

26/4/06

H.E. the Governor

The Hon'ble Mr. G. Stokes C.S.I.

27.4.06.

28/4/06.

E. I. Form No. 1.

CURRENT No. 5025
PASSED ON BY } 2.5.06
R. C. S.
U. R. C.
REF.
R. K.
S. O.

PUBLIC WORKS DEPARTMENT,
IRRIGATION BRANCH.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Improving the large inspection bungalow at Periyar

READ the following

From the Supg. Engineer, VI Circle, dated 10-3-06, No.14 C.E.

Note by the Chief Engineer
for Irrigation.

The Supg. Engineer, VI Circle, submits an estimate amounting to Rs.620 for improving the large bungalow at Periyar which is now being used as a rest house by inspecting officers. As the roof of the bungalow has only a covering of corrugated iron sheets, it is stated that much inconvenience is felt by the occupants ~~both~~ during the hot ~~and rainy~~ seasons. It is, therefore, proposed to provide wooden ceiling underneath the roof throughout -- including the. verandahs. The estimate is recommended for sanction.

Issue
D.I. 30/4/06

Order. No. 4719, d/3-5-1906

The following estimate is sanctioned:-

Imperial.

Irrigation.

42 Major Works (Working Expenses)

Periyar Project.
Madura Division.

I Extensions and Improvements.

I Head works.

K Buildings.

Improving the large bungalow at Periyar.

Estimate. ------ Rs620.

2. This sanction is registered as

No. 26 — I of 1906-07.

T.W.E.S.S.
26/4/06

26/4/06

To

The Chief Engineer for Irrign.

,, Supg. Engineer, VI Circle,

with estimate.

,, Examiner, P.W.Accounts.

24-4-06

DESPATCHED
16 MAY 1906